P.O. Box **266** 18631 Greensboro, NC 27419 (919) 668-4821 RECEIVED N.C. Dept. NRCO

APR 24 1991

Vinston-Salem Regional Office

April 22, 1991

Tom Salley NCDEHNR 8025 North Point Blvd Suite 100 Winston-Salem, NC 27106

Re: Tommy Nelson

8 Northline Place

Greensboro, NC 27410

Site: 5052 Foxburrow Road/Guilford County/27406

Dear Mr. Salley;

On 4/16/91 we removed one 2000 gallon gas tank from the above residence address. The tank measured 12 feet by 64 inches and was buried 5 feet below surface grade. The pump was located at the north end of the tank.

After the tank was pumped, purged of oxygen, and removed, two soil samples were taken two feet below the north end and the south end of the tank. The samples were collected from the floor of the hole at a depth of 12 feet using the bucket of our backhoe. The samples were stored in an ice cooler until delivery at the lab the same day.

Attached is the base map, site map, soil sample report dated April 18, 1991, and the chain of custody form for the samples. Form GW/UST-2 is also enclosed. Based on the information in this report and our observations on site, we feel this site can be closed.

The owner of the property, Mr. Tommy Nelson, is seeking a loan on this property. His bank is requesting a letter from your office indicating the status for closure of this site. If I can be of further help please call me.


J holi

Íhad Chesson

cc: Tommy Nelson Joseph Bryant

Terry Cole

Scott Halstead



00 Gallow A #2115

Woody Mill Road

€ to 421

April 18, 1991

REPORT OF ANALYSIS

JOB #:

PES10416

CUSTOMER:

Piedmont Environmental

ATTN: Thad Chesson

P. O. #:

Tommy Nelson

SAMPLE:

2115 2000 GAL GAS NORTH

2116 2000 GAL GAS SOUTH

RESULTS

2115

2116

Total Petroleum Hydrocarbons (ppm) as Gasoline by EPA Method 5030

(10

₹10

Guilford Laboratories, Inc.

J. A. Rayburn

Chain Of Custody Form

Mekse		
2		
_		
7 II 6		X

Time	Recieved by: Date: 4/16/2/ Time 2:3 (p/a) Relinquished by: Date: // Time : (p/a)	Relinquished by: Date: 4/6/7/ Time 12:15 @ a):	Zoop gas seath 5 take recorder TPH	

Guilford Labs Phone :

919-854-2320

Contact local fire marshall No. Gallons Dimensions Contents Dimensions Contents Dimensions Dimen			Site	Investigation Repo	ort Fo	r Pe	rmane	ent C	losure	of U.S	и.		
Propose correlate and return withn (30) down tolowing completion of all investigation. Regional Office	TANK IN	FOR Return Completed Form To: TANKS IN Regional Office according to the county of the facility's location. [SEE MAP ON REVERSE SIDE OF OWNER'S COPY (BLUE) FOR REGIONAL								Sate U I.D. N Date	Jse Only lumber Received	C. Dept. NACD 17PR 2 4 1991	
Tommy Next xNel son Tommy Sale Tommy Sale Tommy Sale Tommy Next Son Tommy Next S	INSTRUCTIONS								4				
Tommy MekkkNnlson Faith Ware or Company Substituting Place Ont Advance Continue Place Ont Advance Control Place Ont Advance Substituting Place Ont Advance Control Place Control Place Tommy Nelson Name Name Note: Control Precion Name Note: Control Precion No				(4)	in (30) d	lays fol	lowing co	mpletio			f Tank(s)	ediousi onice	
R Northline Place Surl Ford Greensboro, NC 27410 State 7 ip Code State North July 851-1908 So Code 1 leephone Number Name Towns, Nelson Owner Towner Towns, Nelson Owner Towns, Nelson Owner (Value) State V. Lost Information No. Safer No. We save and Condition Town No. Safer No. We save and Condition Town No. Safer Town No. Saf	<u> </u>		Ownership of Tank	(s)					111.		, vesino,		1
R Northline Place Surl Ford Greensboro, NC 27410 State 7 ip Code State North July 851-1908 So Code 1 leephone Number Name Towns, Nelson Owner Towner Towns, Nelson Owner Towns, Nelson Owner (Value) State V. Lost Information No. Safer No. We save and Condition Town No. Safer No. We save and Condition Town No. Safer Town No. Saf	Venor No	Tom	my NekksNel	SON		} -	Facility	Name o	or Compan	ту			1
Sister Street Research Contact lead for marchall VIII. Clock List Check List Check the activities of special growing and sketch.			orthline Pl	ace		\			<u></u>	<u></u>			$\frac{1}{2}$
Guilford Creensoor, NC 27410 y Sute zip Code (919) 855-1908 as Code County 919 637-8441 Freensoor	treet Address						_	505	2 Fox		v Road		
State 219,000 State 190, 855-1908 Name	county	Gre	ensboro. NO	27410		_	Guil	.for	<u>d Gr</u>	<u>eensby</u>			-
Name	City	Sta	te Zip'	Code			County	(91	9)6 <u>97</u>		<u> </u>	·	4
Name	vea Co			nber	III. Con	toot E	-	ode		Teleph	none Number		
Tommy Nelson		NI.	ame	<u>;</u>		ie/ei	G 50H			Tek	ephone Numbe	er .	
Contacts Picture Pic			my Nelson	OWn	er _					(9.	19) 855	-1908	4
Name Name Name Name No. U.S.T. Information V. Excevation Condition V. Madditional Information Required No. Contents No. No. No. No. No. Contents No. No. No. No. No. No. Contents No. No. No. No. Contents No. No. No. DEM in the written report and sketch. VII. Check List	Closure	Contractor _	Piedmont I	Environmental) Во	x 186	31 G	reensbo	10, NC 2/419	4
V. U.S.T. Information V. Excavation Condition V. Additional information Required	Lab				_	oro	, NC		<u>. </u>				
Tank Last Exercises Product Vision Sol Contention No. Gallons Dimensions Contents Yes No Yes						V Eve	ravation	Conc	lition		VI Additio	onal Information Required	
No. Gallore Dimensions Contants Yes No Yes No Yes No General See reverse side of blue copy (covner's copy) for additional information required by N.C. DEM in the written report and sketch. Will. Check List Check the activities completed. Contact local fire marshall Notly DEM Reponal Office before abandonment. Notly DEM Reponal Office before abandonment. Plans & flush piping into tank. Remove all product and residuals from tank Coan and insport tank in the security of the security o	Tavels				Wate	er In	Fre	98	Notable		VI, Malaitat		7
VII. Check List Check the activities completed. ABANDONMENT IN PLACE Fill tark until material overflows tank opening: Fill tark unti	iank No.									T	See rev	erse side of blue coov	
VII. Check List Check the activities completed. VII. Check List Check the activities completed.				· n .			 				(owner's	s copy) for additional	
VII. Check List Check the activities completed. Contact local fire marshall Notify DEM Regional Office before abandonment. Dean & flush pping into tank. Remove all product and residuals from tank Escavate down to tank. Clean and inspect tank Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submensible pumps and other tank flutnes. Cap or plug all lines except the vent and fill lines. Purge tank of all product & flammable vapors. Cut one or more large holes in the tanks. Backfill the area. Date Tank Permanently closed: 4/16/91 Creative vent in the larks. Date Tank Permanently closed: 4/16/91 Creative vent hole Label tank Signature Colifax, NC VIII. Certification (Read and Sign) Certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owners authorized representative Thad Chesson V.P. Piedmont Environmental VIII. Certification Signature ABANDONMENT IN PLACE Fill tank until makend overflows tank opening; Plug or cap all openings. Backfill inert material used cap or errows event line Solid inert material used - please specify: Signature Date Signed 2 4/22/91	1	2000	12'x64"	gas		x		x		x			
Check the activities completed. Contact local fire marshall													1
Check the activities completed. Contact local fire marshall							-						
Check the activities completed. Contact local fire marshall					 				-	-			
Check the activities completed. Contact local fire marshall				· · · · · · · · · · · · · · · · · · ·	<u> </u>		<u>.</u>		-				
Check the activities completed. Contact local fire marshall										_			
Check the activities completed. Contact local fire marshall													
Contact local fire marshall Notify DEM Regional Office before abandonment. Drain & flush piping into tank. Permove all product and residuals from tank Excavate down to tank. Clean and inspect tank. Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps and other tank fixtures. Cap or plug all lines except the vent and fill lines. Purge tank of all product & flarmrable vapors. Cut one or more large holes in the tanks. Backfill the area. Date Tank Permanently closed: 4/16/91 VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached cocuments, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Thad Chesson V.P. Piedmont Environmental ABANDONMENT IN PLACE Fill tank until material overflows tank opening: Plug or cap all openings. Disconnect and cap or remove vent line Solid inert material used - please specify: Disconnect and cap or remove vent line Solid inert material used - please specify: REMOVAL Create vent hole Label tank Dispose of tank in approved manner. Colfax, NC VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Signature ABANDONMENT IN PLACE Fill tank until material overflows tank openings. Disconnect and cap or remove vent line Solid inert material used - please specify: Disconnect and cap or remove vent line Solid inert material used - please speci					VII. (Check	List						
Contact local fire marshall Notify DEM Regional Office before abandonment. Drain & flush piping into tank. Permove all product and residuals from tank Excavate down to tank. Clean and inspect tank. Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps and other tank fixtures. Cap or plug all lines except the vent and fill lines. Purge tank of all product & flarmrable vapors. Cut one or more large holes in the tanks. Backfill the area. Date Tank Permanently closed: 4/16/91 VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached cocuments, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Thad Chesson V.P. Piedmont Environmental ABANDONMENT IN PLACE Fill tank until material overflows tank opening: Plug or cap all openings. Disconnect and cap or remove vent line Solid inert material used - please specify: Disconnect and cap or remove vent line Solid inert material used - please specify: REMOVAL Create vent hole Label tank Dispose of tank in approved manner. Colfax, NC VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Signature ABANDONMENT IN PLACE Fill tank until material overflows tank openings. Disconnect and cap or remove vent line Solid inert material used - please specify: Disconnect and cap or remove vent line Solid inert material used - please speci		<u></u>		Chan				otod.					7
Drain & flush piping into tank. Remove all product and residuals from tank Remove all product and residuals from tank Clean and inspect tank. Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps and other tank fixtures. Cap or plug all lines except the vent and fill lines. Purge tank of all product & flarmable vapors. Cut one or more large holes in the tanks. Backfill the area. Date Tank Permanently closed: 4/16/91 Certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Thad Chesson V.P. Piedmont Environmental	3.7	Notify DEM			k the a	ctivities	comple	<u>AB</u>					
Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submressible pumps and other tank fixtures. X Cap or plug all lines except the vent and fill lines. Purge tank of all product & flammable vapors. Cut one or more large holes in the tanks. Backfill the area. Date Tank Permanently closed: 4/16/91 VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached clocuments, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Thad Chesson V.P. Piedmont Environmental	Ž Drain & flush piping into tank.						, 						
Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submressible pumps and other tank fixtures. X Cap or plug all lines except the vent and fill lines. Purge tank of all product & flammable vapors. Cut one or more large holes in the tanks. Backfill the area. Date Tank Permanently closed: 4/16/91 VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached clocuments, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Thad Chesson V.P. Piedmont Environmental	Excavate down to tank.						Disconnect and cap or remove vent line						
Cap or plug all lines except the vent and fill lines. Purge tank of all product & flarmable vapors. Cut one or more large holes in the tanks. Backfill the area. Date Tank Permanently closed: 4/16/91 VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Thad Chesson V.P. Piedmont Environmental REMOVAL Create vent hole Label tank Dispose of tank in approved manner Salleway Tank Dispose Colfax, NC VIII. Certification (Read and Sign) Viii. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Signature Date Signed \$\frac{2}{2} \frac{4/22/91}{2} \frac{1}{2} \frac{1}{2	Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections,												
Cut one or more large holes in the tanks. Sackfill the area. Date Tank Permanently closed: 4/16/91	Cap or plug all lines except the vent and fill lines.												
VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Thad Chesson V.P. Piedmont Environmental	Cut one or more large holes in the tanks.						Label tank						
VIII. Certification (Read and Sign) I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Signature Date Signed Thad Chesson V.P. Piedmont Environmental	Backfill the area. Date Tank Permanently closed: 4/16/91						-	_XIDE Fin	spose of ta naitank d	esiiraion. ,		y Tank Dispo	3 a .
certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Signature Date Signed Thad Chesson V.P. Piedmont Environmental	Colfax, NC												
certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. Print name and official title of owner or owner's authorized representative Signature Date Signed Thad Chesson V.P. Piedmont Environmental	VIII. Certification (Read and Sign)												
Print name and official title of owner or owner's authorized representative Signature Date Signed 2 4/22/91	I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the												
Thad Chesson V.P. Piedmont Environmental					tive	<u> </u>	Signa	ature) 7	<u> </u>	· -	Date Signed	\dashv
Inda chebbon VIII 1200mbh 2000						n + ¬ ¬			le cla	er-	-	₹ 4/22/91	
								Office	В	lue Copv -	Owner	<u> </u>	لــ

Safeway Tank Disposal, Inc.

Page / of/

CERTIFICATE OF TANK DISPOSAL

					/ /				
Customer,					Date				
				1.0					
Lee	a month	$-C \Omega U U \Omega$	eyernenc	kiD					
المتوك	dipont 19631 wash		-						
الأكلا	les of the	ω_{0} , $Y X = \varnothing$	Y74/j						
			Trar	nsported by:	Padmont End				
Tank Disposal Number	Size	Weight	Product	Residue - Amount	Origin				
4221	2,000g(1830#	260	1000()	toptono Pd.				
	" 0		(0 -	Decemboro, Y.C.				
					-'				
		Tem	y Ne	LISON	1ANK				
,			7						
			·						
			Total Residue	10 go C.					
Tanks v Underg	Tanks were disposed in accordance with API 1604, 1987 Removal and Disposal of Used Underground Petroleum Storage Tanks. Residue was disposed in accordance with U.S. EPA								

Regulations by licensed subcontractor. Lead free scrap steel was recycled by

United Mets Recyclosion_

SAFEWAY TANK DISPOSAL INC.